

Impurities down to ppb levels in high purity materials such as gallium, tellurium, germanium etc., and special alloys can be determined. The impurities can be metals, non-metals and metalloids. The materials are analyzed in ultra-trace analysis facility of the Centre using state of art analytical techniques.